

PHOTOGRAPHIC INTERPRETATION MEMORANDUM



25X1C

RECONSTRUCTION OF
NORTH VIETNAMESE
THERMAL-ELECTRIC
POWERPLANTS

NPIC/R-82/69

SEPTEMBER 1969

Declass Review by NIMA/DOD

GROUP 1 EXCLUDED FROM
AUTOMATIC DOWNGRADING
AND DECLASSIFICATION

25X1C

CONFIDENTIAL

NO FOREIGN DISSEM

WARNING

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

25X1C

PHOTOGRAPHIC INTERPRETATION REPORT

RECONSTRUCTION OF NORTH VIETNAMESE THERMAL-ELECTRIC POWERPLANTS


SEPTEMBER 1969

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

- i -

25X1C

CONFIDENTIAL
NO FOREIGN DISSEM EXCEPT [REDACTED]



- ii -

NO FOREIGN DISSEM EXCEPT

Approved For Release 2001/11/05 : CIA-RDP78B04560A006600010017-5

RECONSTRUCTION OF NORTH VIETNAMESE THERMAL-ELECTRIC POWERPLANTS

Reconstruction of thermal-electric powerplants (TPP) in North Vietnam is continuing, according to recent low-level aerial photography. The Ben Thuy TPP has been reactivated and major exterior repairs are under way at the Nam Dinh TPP.

During the period of allied bombing, 13 of the 17 TPPs in North Vietnam were struck (Figure 1). Three of these were destroyed and there has been no attempt to rebuild them. Of the remaining ten, the Ben Thuy TPP is the last to be reactivated.

The Ben Thuy TPP, heavily damaged in mid-1965, was subsequently restored, and was damaged again in early 1968. The latest reconstruction of the plant has continued since initial repairs to the disposal system were observed [REDACTED]. Boiler testing may have occurred as early as [REDACTED] but was not confirmed until [REDACTED]. The repair of all essential plant components has now been completed and the observation of smoke rising from the flue system indicates that it is operational (Figure 2).

The first evidence of major exterior repairs to any of the thermal-electric powerplants in North Vietnam has been observed at Nam Dinh. Previously, only minor repairs to the roofs and coal sheds have been observed. At the Nam Dinh TPP, two of the four heavily damaged cooling towers are being repaired (Figure 3). A new coal processing and storage building and an unidentified structure are also under construction. Apparently this plant has been operational since initial repairs were completed in [REDACTED].

25X1D

NPIC Project 172002NC




FIGURE 2. THERMAL-ELECTRIC POWERPLANT, BEN THUY, NORTH VIETNAM

- 1 -

CONFIDENTIAL

25X1C

NO FOREIGN DISSEM EXCEPT [REDACTED]




FIGURE 3. THERMAL-ELECTRIC POWERPLANT, NAM DINH, NORTH VIETNAM

NO FOREIGN DISSEM EXCEPT

CONFIDENTIAL

25X52

- 2 -

25X1D

NO FOREIGN DISSEM EXCEPT

CONFIDENTIAL

25X52

NPIC/R-82/69

25X1C

Approved For Release 2001/11/05 : CIA-RDP78B04560A006600010017-5

Approved For Release 2001/11/05 : CIA-RDP78B04560A006600010017-5